


JOBSKIN INTERIM CARE

Compression Garments

Designed to bridge the gap while your custom-made compression garment is being made. This transitional option helps treatment begin sooner and continue without a break in care. Compression treatment must be prescribed and fitted by a qualified healthcare practitioner.



SIZE GUIDE (cm): MEN'S VEST

BEIGE	BLACK	SIZE	CHEST	WAIST	UPPER ARM
120301	120311	X-Small	90-98	80-88	31-35
120302	120312	Small	98-106	88-96	35-37
120303	120313	Medium	106-114	96-104	37-39
120304	120314	Large	114-124	104-112	39-42
120305	120315	X-Large	124-134	112-120	42-45

MEASUREMENT GUIDE

All measurements are circumferential.

Measuring for a Vest

- Chest – measure chest under axilla
- Waist – measure 'dip' above iliac crests
- Upper Arm – measure at axillary level

GARMENT CARE GUIDE



Do not iron



Do not tumble dry, dry in direct
sunlight or hang on a heater or dryer.
Do not dry clean.



Do not wash in hot water.