

JOBSKIN INTERIM CARE

Compression Garments

Designed to bridge the gap while your custom-made compression garment is being made. This transitional option helps treatment begin sooner and continue without a break in care. Compression treatment must be prescribed and fitted by a qualified healthcare practitioner.

SIZE GUIDE (cm): WOMEN'S VEST

BEIGE	BLACK	SIZE	BUST	WAIST	UPPER ARM
120321	120331	X-Small	82-90	62-70	26-29
120322	120332	Small	91-98	70-78	29-32
120323	120333	Medium	98-107	78-87	32-34
120324	120334	Large	108-118	87-98	34-36.5
120325	120335	X-Large	119-129	99-111	36.5-39

GARMENT CARE GUIDE



Do not iron



Do not tumble dry, dry in direct
sunlight or hang on a heater or dryer.
Do not dry clean.



Do not wash in hot water.



MEASUREMENT GUIDE

All measurements are circumferential.

Measuring for a Vest

- Bust – measure the fullest part of the bust
- Waist – measure 'dip' above iliac crests
- Hips – measure the widest point of buttocks
- Upper Arm – measure at axillary level



Jobskin

Working together for better solutions